

b) (6)

### Re: ASK: Information to reply to a FOIA

1 message

(b) (6) > Mon, Jul 15, 2019 at 11:33 AM To: (b) (6)

Martin

these are the buildings for Region 1. If you require more detail you can contact (b) (6)

Please note I have been reassigned back to D&C in Region 1 and (b) (6) is on temporary detail for the next 120 days in my (b) (6) Position. You can also contact our FMSP Division (b) (6)

- 1. Gignoux Court House, ME0034ZZ, 156 Federal St, Portland, ME, Mold
- 2. Rutland Courthouse, VT0016ZZ, 151 West St, Rutland, VT, Mold (setting up to correct in near future)
- 3. Cleveland Federal Building, NH0030ZZ, 53 Pleasant St, Concord, NH, Mold

there are three buildings that we perform quarterly air monitoring on due to spray on asbestos insulation but all ACM is in good condition

ME0068zz Edmund S. Muskie Federal Building, 40 Western Avenue, Augusta, Maine NH0036zz Thomas J. McIntyre Federal Building, 80 Daniel Street, Portsmouth, New Hampshire CT0059zz Brien McMahon Courthouse, 915 Lafayette Boulevard, Bridgeport, Connecticut

(b) (6)
Energy, Utilities & Environment
Facilities Management Division
U.S. General Services Administration
10 Causeway Street, Floor 11
Boston, MA 02222
Office - (b) (6)
Cell - (b) (6)

On Fri, Jul 12, 2019 at 3:14 PM (b) (6) wrote:

Hello again Team.

I realize that this might look familiar, and I apologize for that, but this ask is very specific. In response to a FOIA, we need you all to please reply to me directly and copy (b) (6) with an answer to this exact question only.

(b) (5)

Please respond to me via email by 1200 noon on Friday July 19, 2019. If you have any question or need any additional clarity on this, please give me a call, or you can reach out to (b) (6).

Thanks Team!

(b) (6)

(b) (6)

Facility Risk Management Division

Office of Facilities Management

GSA, Public Buildings Service Cell (b) (6)





#### IAQ/Mold/ACM R4 Abatement Actions Re: ASK: Information to reply to a FOIA

1 message



Mon, Jul 22, 2019 at 12:4

Hi (b) (6)

Currently GSA R4 is dealing with the following IAQ/Mold issues for immediate abatement.

		(b) (5), (b) (6)
NC0111AB Terry Sanford	310 NEW BERN AVE RALEIGH, NC 27601	(5) (5), (5) (6)
FL0064AE. R L TIMBERLAKE JR FB	500 E ZACK ST TAMPA, FL 33602	
TN0088ZZ CLIFFORD DAVIS-ODELL HORTON	FEDERAL BUILDING MEMPHIS, TN 38103	

At this time we currently don't have any immediate Asbestos (ACM) health exposure which would require abatement. The GSA owned portfolio dose have older buildings that contain ACM material.

Thanks for your support.

Please excuse any typos; sometimes our good intentions are trumped by auto correct and spell check.

Kind regards,

(b) (6) /Fire Protection/Environmental Program

GSA | Public Buildings Service | Southeast Sunbelt Region 4 (4P)
Facilities Management Division | Safety & Environmental Branch (4PQG)
77 Forsyth Street SW, | Atlanta, GA 30303 |

GSA Facility Risk Management Website: https://insite.gsa.gov/organizations/public-buildings-service/facili ies-management/facility-risk-management


#### CONFIDENTIALITY NOTICE:

This email message and any attachments to this email message may contain confidential informa ion belonging to the sender which is legally privileged. The information is intended only for t use of he individual or entity to whom it is addressed. Please do not forward this message without permission. If you are not the intended recipient or he employee or agent responsible for delivering it to the intended recipient, you are hereby notified hat any disclosure, copying, distribution or the taking of any ac ion in reliance on the contents of this transmission is strictly prohibited. If you have received this transmission in error, please notify the sender immediately by telephone or return email and delete and destroy the original email message, any attachme thereto and all copies hereof.

On Fri, Jul 19, 2019 at 11:43 AM(b) (6) wrote

Just reaching out here. Your two regions are he only two we have not heard back from in response to our ASK to fulfill a FOIA. Could you please let to under a least let to original email and ASK are attached. Thanks sincerely.

(b) (6)
(b) (6) Facility Risk Management Division
Office of Facil ties Management
GSA, Public Buildings Service
Cell (b) (6)





(b) (6)

# ASK: Information to reply to a FOIA

1 message



(b) (6)

We only have one issue in Region 6 and it is in a decommissioned building, but materials had been stored in the building: Federal Records Center Building 100 Generator Building, MO0551AG, 9700 Page Boulevard, Overland, MO - Asbestos

Please contact me for additional information. Thank you.

(b) (6) (b) (6)

Facilities Management Division

GSA Public Buildings Service - Heartland Region

Desk: (b) (6) Cell: (b) (6)





### Re: ASK: Information to reply to a FOIA



Mon, Jul 15, 2019 at 9:51 AM

Region 7 Data	gion 7 Data FOIA GSA-2019-001129							
Building #	Building Name	Address	City	State	ZIP	Mold or Asbestos		
AR0030	Richard Sheppard Arnold USCH	600 W Capital Ave	Lit le Rock	AR	72201	Mold		
AR1202	Cherry Brook	1200 Cherry Brook Dr	Lit le Rock	AR	72211	Mold		
LA0029	Monroe FB/CH	201 Jackson St	Monroe	LA	71201	Mold		
OK0074	Lawton FB/CH	410 SW 5th St	Lawton	OK	73501	Mold		
OK1356	Robinson Plaza	55 N Robinson Ave	Oklahoma City	OK	73102	Mold		
TX0019	Jack Brooks FB	300 Willow St	Beaumont	TX	77701	Mold		
TX1739	Military Entrance Process Station	1100 Fillmore St	Amarillo	TX	79101	Mold		
TX2471	Balch Springs SSA	2300 Dunson Dr	Balch Springs	TX	75180	Mold		
TX2569	Marshall SSA	1509 Sedberry St	Marshall	TX	75670	Mold		
TX2584	Cleburne SSA	Business 67 & W Henderson St	Cleburne	TX	76033	Mold		
TX2638	Brenham SSA	2901 Victory Lane	Brenham	TX	77833	Mold		
TX2663	Corsicana SSA	221 S 45th St	Corsicana	TX	75110	Mold		

Safety, Environmental, and Fire (b) (6) GSA Region 7 Office ) (6) Cell

On Fri, Jul 12, 2019 at 2:14 PM(b) (6) Hello again Team.

I realize that his might look familiar, and I apologize for that, but this ask is very specific. In response to a FOIA, we need you all to please reply to me direc ly and copy , wi h an answer to this exact question only.

Please respond to me via email by 1200 noon on Friday July 19, 2019. If you have any question or need any additional clarity on his, please give me a call, or you can reach out to (b) (6)

Thanks Team!

(b) (6) Facility Risk Management Division Office of Facilities Management GSA, Public Buildings Service


Cell (b) (6)



) (6)

# Information to reply to a FOIA - Current Mold/Asbestos Problems

1 message



- This requested information was previously provided to (b) (6) on 6/27/2019 but please see below for the request information for Region 8

#### Mold problem

Old Piegan Pumphouse, Piegan, MT Land Port of Entry. GSA Building Number MT0561AE. This is an unoccupied building that currently only houses the emergency generator for the port. (b) (5)

#### Asbestos problem

None

Please let us know if you need anything else.



GSA U.S. General Services Administration
GSA-PBS Region 8
Office of Facilities Management (OFM)
Denver Federal Center | Building 41

Denver, CO 80225 P: (b) (6)

Commitment you Deserve. Experience you Trust.



(b) (6)

# Re: ASK: Information to reply to a FOIA (Region 11)

1 message



As part of our due diligence on this task we have checked IRIS work items, NCMMS and JIRA work tickets, our Project Tracker system

and the NCR Asbestos Abatement Permit log.



(c) (d)

#### GSA Regional Office Building

DC0031ZZ 301 7th Street, SW Washington, DC Mold (localized)

### **Washington National Records Center**

MD0056AG 4205 Silver Hill Road Suitland, Maryland Mold (building)

### FRC Building 403-Turbines

MD0737WT

10903 New Hampshire Ave

Silver Spring, MD

Asbestos (localized)

-----

#### Respectfully



Construction Safety and Occupational Health (b) (6)